

Current USA
Replacement Part Detail Report



Item	Description: SunDial Pendant	Model 1055	Model 1056					Notes
1965	Glass HQI cover; Models 1055, 1056	1	1					
1749	Surface Mount GY10Q Lamp Socket ; Models 1001 - 1002	2	2					
1909	HQI Socket	1						150W
1908	HQI Reflector	1						150W
1953	250w HQI Socket Model 1056 1075-1079 and 1160-1166		1					
1954	250w HQI Reflector Model 1056 1075-1079 and 1160-1166		1					
1952	(1) 1x250 watt ballast assembly		1					
1763	Ballast 1x32w 1x40w (no enclosure)	2	2					
1907	Ballast 150 watt (no enclosure)	1						
1767	2 3/8" Fan	1	1					add 1055
1784	Timer		2					
1093	Hanging Kit	1	1					